

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

October 25, 2011

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavergc.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	07200-001A
Date of Submittal:	October 21, 2011
Title:	Vapor Barrier and Insulation for Batts and Ceilings
Specification Section:	07200
Manufacturers:	Owens Corning; Poly-America

The referenced submittal has been stamped "**No Exception Taken**" and "**Make Corrections Noted**". Our comments are as follows:

1. We acknowledge receipt of the Contractor's review comments provided as an attachment to this submittal. The Kraft faced batts were specified in addition to the polyethylene vapor barrier for ease of installation. If the Contractor desires to not install the Kraft faced material, we will trust the Contractor's judgment regarding installation on whether to use Kraft faced batts or non-faced batts. If Kraft faced batts are utilized, we will not prepare a letter absolving the Contractor of liability. If Weaver Construction Management, Inc. desires to furnish the letter, that is at their discretion.
2. The Kraft faced fiber glass insulation: **No Exception Taken**
3. The raft-R-mate[®] attic rafter vents: **No Exception Taken**
4. The polyethylene plastic sheeting: **No Exception Taken**
5. As a point of clarification, in a recent discussion with Horace Myers with Weaver Construction Management, Inc., it was his understanding the raft-R-mate[®] attic rafter vents were placed in the soffit. Based on our review, the attic rafter vents are placed in the area between the attic and the soffit area. A vented metal soffit panel is still required at the bottom of the soffit as shown on the Construction Drawings.

Mr. Wes Weaver
October 25, 2011
Page 2

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavergc.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavergc.com

Mr. Tyler Ammerman, Weaver Construction Management, Inc., tammerman@weavergc.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.