GMS, INC.

CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

March 23, 2011

Mr. Wes Weaver, President Weaver General Construction Co. 3679 South Huron Street, Suite 404 Englewood, CO 80110 Via Email to: wes@weavergc.com Hard Copy to Follow

Re:

Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)

Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:

03200-003A

Date of Submittal:

February 15, 2011

Title:

Digester and Aeration Basin Wall Reinforcing, Submittal

Drawings P2 and P3

Specification Section:

03200

Supplier:

Dalco Industries, Inc.

The referenced submittal has been stamped "No Exception Taken". No additional information or resubmittal is required on this item. Our comments are as follows:

- 1. Drawing P2: The wall plan showing corner bars CB1 is acceptable as shown.
- 2. Drawing P3:
 - a. Elevation E showing the strut dowel legs splayed is acceptable as shown.
 - b. The top of wall section showing the segmented strut shall be acceptable. Do not provide a blockout in the walls for the struts.

Please call if you should have any questions.

Sincerely,

Mark A. Morton, P.E.

MA SE

MAM/kmw

ec (letter only except as noted):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@Ifmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@qwestoffice.net

Mr. Jeff Burst, Project Superintendent, Weaver General Construction Co., jeff@weavergc.com

Ms. Leslie Brown, Weaver General Construction Co., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc. (w/enclosure)