## GMS, INC.

## CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

July 25, 2011

Mr. Wes Weaver, President Weaver Construction Management, Inc. 3679 South Huron Street, Suite 404 Englewood, CO 80110

Via Email to: wes@weavergc.com No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)

Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.: 03600-002A

Date of Submittal: July 22, 2011

Title: Injectable Grout

Specification Section: 03600 Grout

Manufacturer: Green Mountain International, LLC

The referenced submittal has been stamped "No Exception Taken" except as stated below. No additional information or resubmittal is required on this item. Our comments are as follows:

1. If a crack is found to be greater than  $1/16^{th}$  inch or greater in width, we request the Contractor and/or their subcontractor contact us to discuss the crack sealing procedure that will be implemented prior to the work being accomplished.

Please call if you should have any questions.

Sincerely,

David R. Frisch, P.L.S.

David R. Firsch

DRF/Ime

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavergc.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavergc.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavergc.com

cc (letter only):

Mr. Jerry Miller, Resident Project Representative, GMS, Inc.