

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLENNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

July 3, 2013

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
c/o Garney Construction
7911 Shaffer Parkway
Littleton, CO 80127

***Via Email to: wes@weavercm.com
No Hard Copy to Follow***

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.: 08100-002A
Date of Submittal: July 1, 2013
Title: Door Frames and Doors for Biosolids Building
Specification Section: 08100
Manufacturers: Cal-Royal Products, Inc.; Hager Co.; Ives; Pioneer Industries;
Precision; Reese; Stanley; Simplex; Schlage; Ilco

Submittal No.: 08710-006A
Date of Submittal: July 1, 2013
Title: Door Hardware for Biosolids Building
Specification Section: 08710
Manufacturers: Newco Door & Hardware, LLC; Cal-Royal Products, Inc.;
Hager Co.; Ives; Pioneer Industries; Precision; Reese; Stanley;
Simplex; Schlage; Ilco

The referenced submittal has been stamped "***No Exception Taken***". Our comments are as follows:

1. Page 3 of the shop submittal provides three Job Note(s). We are responding to the three notes as follows:
 - 1) Please verify all jamb depths prior to returning submittals.

Response: Jeff Burst with WCMI will verify the depth required and provide this information to the supplier.

Mr. Wes Weaver
July 3, 2013
Page 2

- 2) Hardware sets reflect the hardware sets specified. Please verify all hardware sets are correct. We have incorporated the use of Hager lock sets and Stanley closers since these were used in other buildings.

Response: GMS, Inc. previously reviewed and approved a hardware set. If there is any deviation from the approved set, please indicate so. Otherwise an additional review will not be accomplished.

- 3) Please verify if the frames for openings D-BH1, D-BH3, and D-BH4, are to be 86" tall, or 88" tall. Architect/engineer has ask that we coordinate these with you.

Response: Jeff Burst with WCMI will verify the height required and provide this information to the supplier.

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavercm.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavercm.com

Mr. Adam Roeder, Weaver Construction Management, Inc., aroeder@weavercm.com

Ms. Solange Huggins, Project Engineer, Garney Construction, shuggins@garney.com

cc (w/attachments): Mr. Jerry Miller, Resident Project Representative, GMS, Inc.