

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

October 25, 2011

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavergc.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	08301-001A
Date of Submittal:	October 21, 2011
Title:	ThermaSeal Insulated Overhead Door – Windload Data
Specification Section:	08301
Manufacturer:	Raynor

The referenced submittal has been stamped "**No Exception Taken**", "**Revise and Resubmit**" and "**Submit Specified Item**". No additional information or resubmittal is required on this item. Our comments are as follows:

1. Track and track fasteners: **Submit Specified Item**
 - a. We request the base material of the track bolts and the type of rust inhibiting coating that will be utilized be provided.
2. Solid shaft and key stock: **No Exception Taken**
3. Bearing plates and bearing: **No Exception Taken**
4. Hinges, top fixtures, bottom fixtures, hinge fasteners: **No Exception Taken**
5. Roller stem bearings: **No Exception Taken**
6. Perforated angle iron: **No Exception Taken**
7. Cables: **No Exception Taken**
8. Springs: **No Exception Taken**
9. "TEK" screws for top and bottom fixtures: **No Exception Taken**
 - a. Please provide the rust inhibiting coating proposed for use.

Mr. Wes Weaver
date
Page 2

10. Drums and cones: **No Exception Taken**

a. Please provide the rust inhibiting coating proposed for use.

11. Coupler: **Revise and Resubmit**

a. We request alternate materials be utilized in lieu of the cast iron coupler. Cast iron is extremely susceptible to corrosion.

b. In addition, please provide the rust inhibiting coating proposed for use.

12. Roller bearing: **No Exception Taken**

13. 100 mph windload certification: **No Exception Taken**

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavergc.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavergc.com

Mr. Tyler Ammerman, Weaver Construction Management, Inc., tammerman@weavergc.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.