

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

October 10, 2012

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavercm.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	08630-001
Date of Submittal:	September 10, 2012
Title:	Serious Energy Windows for Operations Building
Specification Section:	08630 – Fiberglass Reinforced Plastic Windows
Manufacturers:	Dow Corning Corporation; Ken Caryl Glass Inc.; Serious Energy, Inc.; Truth Hardware

The referenced submittal has been stamped "**No Exception Taken**" and "**Make Corrections Noted**". Our comments are as follows:

1. We acknowledge receipt of the additional submittal review comments provided by Weaver Construction Management, Inc. The *Additional Submittal Review Comments* state, "The exterior windows are supposed to be 36" X 8". Ken Caryl Glass is requesting that they be 36" X 14". Their supplier cannot make widows [windows] smaller than 14".
 - a. The proposed exterior windows noted above are to be 60" in width, not 36". **Make Corrections Noted**
 - b. We have discussed this with the Contractor and based upon our discussion the Contractor has indicated the framing can be accomplished above the proposed casework in the Operations Building. **No Exception Taken**
2. Dow Corning Corporation, *Dow Corning*[®] Contractors Weatherproofing Sealant: **No Exception Taken**
 - a. The Contractor shall select the color most suitable for matching the existing building. If visible from the exterior, it would appear the Sandstone may be a close match. If visible from the interior, we request the Contractor coordinate with the Owner to confirm the color scheme for the inside of the building.

Mr. Wes Weaver
October 10, 2012
Page 2

3. Window Frames

- a. Page 1 of 3, Frame Width: 60", Frame Height: 36", Number Required: 3, Frame Type: Awning: **No Exception Taken**
- b. Page 2 of 3, Frame Width: 60", Frame Height: 14", Number Required: 2, Frame Type: Fixed: **No Exception Taken**
- c. Page 3 of 3, Frame Width: 36", Frame Height: 36", Number Required 2, Frame Type: Fixed: **No Exception Taken**

4. Serious Energy, Inc., SeriousWindows™ 325: **No Exception Taken**

- a. The color options indicate the interior and exterior color will be Bronze. We request the color be coordinated with the Owner to ensure the Bronze color is acceptable. Actual color samples for the window should be provided to the Owner for review and selection.

5. Truth Hardware, Encore® Operator: **No Exception Taken**

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavercm.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavercm.com

Mr. Adam Roeder, Weaver Construction Management, Inc., aroeder@weavercm.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavercm.com

cc (letter only): Mr. Jerry Miller, Resident Project Representative, GMS, Inc.