

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

October 19, 2012

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavercm.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	08710-005
Date of Submittal:	September 27, 2012
Title:	Hollow Metal Doors/Frames & Finish Hardware for Blower Building
Specification Sections:	08100 – Metal Doors and Frames 08710 – Finish Hardware
Manufacturers:	Cal-Royal Products, Inc.; Hager Co.; Ives; Pioneer Industries; Precision; Reese; Stanley

The referenced submittal has been stamped "**No Exception Taken**" and "**Revise and Resubmit**". Our comments are as follows:

1. We acknowledge the Job Note(s) provided by the manufacturer/supplier. We request the Contractor review these comments with the manufacturer/supplier and address all issues.
2. Door D-BB4 with Hardware Set A: **No Exception Taken**
 - a. Please note, the vision lite is to be placed on the hinge side of the door.
3. Door D-BB1 with Hardware Set D: **Revise and Resubmit**
 - a. Please reference the Engineer's Supplemental Instructions (ESI) No. Twenty-Three (23) dated October 10, 2012. Door D-BB1 shall be changed to a Type C door with a swing of right-hand reverse. The door size will be a 4'-0" x 7'-0" door. The revised door shall be equipped with Hardware Set B rather than Hardware Set A as noted on the ESI. Please confirm the new door is equipped with the appropriate length threshold, sweep, kickplate, etc. for a 4'-0" wide door.

Mr. Wes Weaver
October 19, 2012
Page 2

4. Door D-BB3 with Hardware Set F: **Revise and Resubmit**

- a. The submitted Hardware Set includes a Stanley Rim Exit which is not needed. Please reference Addendum No. Six (6) for Hardware Set F requirements.

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavercm.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavercm.com

Mr. Adam Roeder, Weaver Construction Management, Inc., aroeder@weavercm.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavercm.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.