GMS, INC.

CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

July 6, 2011

Mr. Wes Weaver, President Weaver General Construction Co. 3679 South Huron Street, Suite 404 Englewood, CO 80110 Via Email to: wes@weavergc.com No Hard Copy to Follow

Re:

Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:

09251-001

Date of Submittal:

June 30, 2011

Title:

HardieBoard® 500 Board and FireBloc® Type X Gypsum

Wallboard

Specification Section:

09251

Manufacturers:

JamesHardie Building Products, Inc.; American Gypsum

The referenced submittal has been stamped "No Exception Taken" and "Make Corrections Noted". Our comments are as follows:

- 1. HardieBoard[®] 500 Board: *Make Corrections Noted*
 - Confirm that the product proposed for delivery will have a factory-primed surface ready for coating in accordance with Specification Section 09900.
- 2. FireBloc[®] Type X Gypsum Wallboard: **No Exception Taken**

Please call if you should have any questions.

Sincerely,

David R. Frisch, P.L.S.

and P. Fisch

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Superintendent, Weaver General Construction Co., jeff@weavergc.com

Mr. John Jacob, Project Manager, Weaver General Construction Co., john@weavergc.com

Ms. Leslie Brown, Weaver General Construction Co., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.