

**GMS, INC.**  
CONSULTING ENGINEERS  
611 NORTH WEBER, SUITE 300  
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935  
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.  
ROGER J. SAMS, P.E.  
GREGORY R. WORDEN, P.E.  
THOMAS A. McCLENNAN, P.E.

KEN L. WHITE, P.L.S.  
DAVID R. FRISCH, P.L.S.  
MARK A. MORTON, P.E.  
JASON D. MEYER, P.E.

March 6, 2012

Mr. Wes Weaver, President  
Weaver Construction Management, Inc.  
3679 South Huron Street, Suite 404  
Englewood, CO 80110

***Via Email to: wes@weavercm.com***  
***No Hard Copy to Follow***

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)  
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	09252-001
Date of Submittal:	February 22, 2012 and March 6, 2012
Title:	Steel Stud Framing in Interior Rooms at EM Building
Specification Section:	09252
Manufacturer:	Cemco Steel

The referenced submittal has been stamped "***No Exception Taken***". Our comments are as follows:

1. The Contractor's supplier, Tri City Drywall, Inc., provided the following explanation for the materials to be provided. Based upon the explanation, we taken no exception to this submittal.
  - a. 14 gage structural studs (68 mil thickness)
    - 1) 2" x 4"
      - Member 362S represents a 3<sup>5</sup>/<sub>8</sub>-inch web depth
      - The 137 represents a 1<sup>3</sup>/<sub>8</sub>-inch flange width
      - The 68 represents the mil thickness
    - 2) 2" x 6" and 2" x 8"
      - 600 and 800 represent 6 inch and 8 inch full dimension studs
  - b. 20 gage structural studs (33 mil thickness)
    - 1) 2" x 4"
      - Member 362S represents a 3<sup>5</sup>/<sub>8</sub>-inch web depth
      - The 137 represents a 1<sup>3</sup>/<sub>8</sub>-inch flange width
      - The 33 represents the mil thickness

Mr. Wes Weaver  
March 6, 2012  
Page 2

- 2) 2" x 6" and 2" x 8"
  - 600 and 800 represent 6 inch and 8 inch full dimension studs
2. If the information provided above is not in accordance with those materials being supplied, we request additional information be submitted providing clarification.

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

- Mr. Jim Heckman, Manager, LFMSDD, [lfmanager@lfmsdd.org](mailto:lfmanager@lfmsdd.org)
  - Ms. Cindy Murray, Office Manager, Fountain Sanitation District, [fsdistrict@fsd901.org](mailto:fsdistrict@fsd901.org)
  - Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., [jeff@weavercm.com](mailto:jeff@weavercm.com)
  - Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., [john@weavercm.com](mailto:john@weavercm.com)
  - Mr. Tyler Ammerman, Weaver Construction Management, Inc., [tammerman@weavercm.com](mailto:tammerman@weavercm.com)
  - Ms. Leslie Brown, Weaver Construction Management, Inc., [leslie@weavercm.com](mailto:leslie@weavercm.com)
- cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.