

REQUEST FOR INFORMATION

Request for Information -	19	ROUTING	DATE SENT	VIA MAIL, EMAIL OR FAX			DATE RECEIVED	VIA MAIL, EMAIL OR FAX		
				M	E	F		M	E	F
OWNER: LFMSDD		Contractor to Engineer	10/21/2011		X					
PROJECT: HDTRWRF		Engineer to Contractor	10/27/2011		X					
ENGINEER: GMS, Inc.		Copy to Owner								
CONTRACTOR: Weaver Construction Management Co.										
RFI TITLE: Stair Treads										
REFERENCE: HW-7 Sec. D										
CONTRACTOR'S REQUEST										
The following information, interpretation, or clarification is requested as described below or in the attachments.										
BCCI requests clarification, due to recent code issues, that there is no toe kick space on the stairs and that there is no imbedded nosings.										
By: Jeff Burst Date: 10/21/2011										
ENGINEER'S RESPONSE										
The following information, interpretation, or clarification is provided as described below or in the attachments.										
Provide construction in accordance with the PPRBD approved plans. No toe kick space or imbedded non-slip step nosings are required.										
By: Roger J. Sams, P.E., GMS, Inc. Date: October 27, 2011										

cc: Wes Weaver, Jeff Burst, John Jacob, WGCC; Jim Heckman, LFMSDD; Tim Long, Charlie Edgar, Cindy Murray, FSD; Al Testa, CCMD; Roger Sams, Dave Frisch, Jerry Miller, GMS, Inc.; Pat Danenberg, MWI; John Peiffer, Mike Gaines, MGA; Mark Reasinger, PECI