

**GMS, INC.**  
CONSULTING ENGINEERS  
611 NORTH WEBER, SUITE 300  
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935  
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.  
ROGER J. SAMS, P.E.  
GREGORY R. WORDEN, P.E.  
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.  
DAVID R. FRISCH, P.L.S.  
MARK A. MORTON, P.E.  
JASON D. MEYER, P.E.

April 4, 2012

Mr. Wes Weaver, President  
Weaver Construction Management, Inc.  
3679 South Huron Street, Suite 404  
Englewood, CO 80110

*Via Email to: wes@weavergc.com  
No Hard Copy to Follow*

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)  
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	13121-001C – For Information Only
Date of Submittal:	April 3, 2012
Title:	Equipment and Maintenance (EM) Building Prefabricated Metal Building – Email Correspondence
Specification Section:	13121 – Prefabricated Metal Building
Manufacturer:	Chief Buildings/Chief Industries, Inc.

The referenced submittal has been stamped "**No Exception Taken**". Our comments are as follows:

1. We acknowledge receipt of the explanation on the variation in the bolt hole configuration proposed on the base plates for the Equipment and Maintenance Building.
2. Please note, use of a torch to modify hole locations in the base plates is not an acceptable alternative. All bolt holes on the base plates must match the as-constructed locations of the anchor bolts cast into the pilasters.

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, [lfmanager@lfmsdd.org](mailto:lfmanager@lfmsdd.org)  
Ms. Cindy Murray, Office Manager, Fountain Sanitation District, [fsdistrict@fsd901.org](mailto:fsdistrict@fsd901.org)  
Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., [jeff@weavercm.com](mailto:jeff@weavercm.com)  
Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., [john@weavercm.com](mailto:john@weavercm.com)  
Mr. Tyler Ammerman, Weaver Construction Management, Inc., [tammerman@weavercm.com](mailto:tammerman@weavercm.com)  
Ms. Leslie Brown, Weaver Construction Management, Inc., [leslie@weavercm.com](mailto:leslie@weavercm.com)  
Mr. Mike Gaines, P.E., MGA Structural Engineers, Inc., [mg@mgase.com](mailto:mg@mgase.com)

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.