GMS, INC.

CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

March 31, 2011

Mr. Wes Weaver, President Weaver General Construction Co. 3679 South Huron Street, Suite 404 Englewood, CO 80110 Via Email to: wes@weavergc.com No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)

Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.: 03200-005

Date of Submittal: February 7, 2011

Title: Concrete Reinforcement for Drilled Piers at Secondary

Clarifiers, Submittal Drawing P13

Specification Section: 03200

Supplier: Dalco Industries, Inc.

The referenced submittal has been stamped "Make Corrections Noted". No additional information or resubmittal is required on these items. Please ensure that all comments below are satisfactorily addressed prior to fabrication and/or delivery of the reinforcing. Our comments are as follows:

- Drilled Pier Schedule
 - a. Revise MK P3 to indicate a quantity of 3.
 - b. Revise MK P4 to indicate dowel "projected" length to be a minimum of 1'-4" if possible.
 - c. Revise MK P11 to indicate dowel "projected" length to be a minimum of 1'-4" if possible.
- 2. Provide additional #6 and #7 reinforcing bar for splicing if piers are longer when drilled.
- 3. Revise Section B to note 1'-4" if possible on the projected length of the dowels.
- 4. Revise the Pier Plan @ Secondary Clarifier No. 2 to indicate the pier at the 6 o'clock position to be P1.

Mr. Wes Weaver, President March 31, 2011 Page 2

5. Please ensure all reinforcing will be ASTM A615, Grade 60 steel.

Please call if you should have any questions.

Sincerely,

David R. Frisch, P.L.S.

David R. Frisch

DRF/kmw

ec (letter only except as noted):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@qwestoffice.net

Mr. Jeff Burst, Project Superintendent, Weaver General Construction Co., jeff@weavergc.com

Ms. Leslie Brown, Weaver General Construction Co., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc. (w/enclosure)