

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLENNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

December 12, 2011

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

*Via Email to: wes@weavergc.com
No Hard Copy to Follow*

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	03300-009I
Date of Submittal:	December 8, 2011
Title:	Additional Information: Ultra Fiber 500 Reinforcement Fiber for Concrete Mix Design A70F for Aeration Basin & Digester Structure Walls & Columns; Pump Room Walls of Headworks Structure
Specification Section:	03300
Manufacturer:	Buckeye Building Fibers LLC

The referenced submittal has been stamped "**No Exception Taken**". No additional information or resubmittal is required on this item. Please call if you should have any questions.

Sincerely,



Roger J. Sams, P.E.

RJS/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org
Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@gwestoffice.net
Mr. Jeff Burst, Project Superintendent, Weaver General Construction Co., jeff@weavergc.com
Mr. John Jacob, Project Manager, Weaver General Construction Co., john@weavergc.com
Ms. Leslie Brown, Weaver General Construction Co., leslie@weavergc.com
Mr. Mike Gaines, P.E., MGA Structural Engineers, mg@mgase.com

cc (letter only):

Mr. Jerry Miller, Resident Project Representative, GMS, Inc.