## GMS, INC.

## CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

March 28, 2012

Mr. Wes Weaver, President Weaver Construction Management, Inc. 3679 South Huron Street, Suite 404 Englewood, CO 80110 Via Email to: wes@weavercm.com No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)

Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.: 05500-011

Date of Submittal: March 28, 2012, 1:53 p.m.

Title: Secondary Clarifier Splitter Structure & Lapeyre Stair

Specification Section: 05500 – Metal Fabrications

Manufacturers: CMS Industrial Constructors: Lapevre Stair, Inc.

The referenced submittal has been stamped "No Exception Taken". Our comments are as follows:

- 1. We acknowledge receipt of the comments provided by WCMI including coating of the embed angle and lowering the landing elevation 1 inch to accommodate a 36-inch stair.
- 2. The "Description" on the Lapeyre Stair, Inc. detail sheet indicates the stairs are to be, "36 Inch 56 Degree Carbon Steel Stair, Galvanized with Standard Narrow Handrail." We take no exception to the proposed stairs with a riser height of 7.2 inches, the overall 36-inch height, the 56 degree carbon steel stair with hot-dipped galvanizing.
- Secondary clarifier splitter structure grating and embed material:
  - a. Sheet 1
    - 1) We take no exception to the dimensioning as shown; however, the outside dimensions shown appear to be approximately ½-inch long.
  - b. Sheet 2
    - 1) We take no exception to the layout of the embed material. Again we note the outside dimensions to be approximately ½-inch longer than shown on the drawings.

Mr. Wes Weaver March 28, 2012 Page 2

- c. Sheet 3 no exception taken
- d. Sheet 4 no exception taken

Please call if you should have any questions.

Sincerely,

David R. Frisch, P.L.S.

David R. Firsch

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@Ifmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavercm.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavercm.com

Mr. Tyler Ammerman, Weaver Construction Management, Inc., tammerman@weavercm.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavercm.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.