

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLEARNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

August 3, 2012

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavercm.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	05500-017
Date of Submittal:	July 30, 2012
Title:	UV Channel Level Control Weir
Specification Section:	05500 – Metal Fabrications
Manufacturer:	CSM Industrial Constructors; Ozonia North America

The referenced submittal has been stamped "***Make Corrections Noted***". Our comments are as follows:

1. We take no exception to the overall dimensions presented on submittal drawing E1 as they are consistent with the dimensions given on the Project Drawings. However, it is requested WCMI verify actual field dimensions of the channel prior to fabrication to ensure a proper fit of the level control weir within the channel.
2. The plan view of the level control weir on submittal drawing No. 1 indicates "BENT BAFFLE PLATE #c3 – 8 PLACES". It appears this note should reference BENT BAFFLE PLATES #b3 rather than #c3 as indicated. Please verify and correct accordingly.
3. Sealant shall be installed around all edges of the level control weir after it is anchored in place to ensure a completely watertight installation.
4. As the above comments are relatively minor in nature, a resubmittal package for this item is not required. All field verification requested above shall be completed by WCMI and coordinated with their suppliers prior to fabrication of the level control weir.

Mr. Wes Weaver
August 3, 2012
Page 2

Please call if you should have any questions.

Sincerely,



Mark A. Morton, P.E.

MAM/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavercm.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavercm.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavercm.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.