

GMS, INC.
CONSULTING ENGINEERS
611 NORTH WEBER, SUITE 300
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.
ROGER J. SAMS, P.E.
GREGORY R. WORDEN, P.E.
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.
DAVID R. FRISCH, P.L.S.
MARK A. MORTON, P.E.
JASON D. MEYER, P.E.

November 30, 2011

Mr. Wes Weaver, President
Weaver Construction Management, Inc.
3679 South Huron Street, Suite 404
Englewood, CO 80110

Via Email to: wes@weavergc.com
No Hard Copy to Follow

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:	06100-001B
Date of Submittal:	November 16, 2011
Title:	Roof Truss Drawings and Configurations: Lumber, Plywood, Metal Framing Anchors, Metal Connector Plates, Hardware and Fasteners
Specification Section:	06100 – Carpentry
Manufacturers:	Simpson; MiTek

The referenced submittal has been stamped "**No Exception Taken**". No additional information or resubmittal is required on these items.

1. Simpson Strong-Tie: **No Exception Taken** to the following:

- a. MTHM-2 Truss Hangers
- b. LUS26 Face Mount Hangers
- c. LS30 Reinforcing and Skewable Angles
- d. H2.5T Hurricane Ties

2. Mi-Tek Wood Species and Grade: **No Exception Taken**

Please call if you should have any questions.

Sincerely,



David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, lfmanager@lfmsdd.org
Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org
Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavergc.com
Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavergc.com
Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavergc.com
Mr. Michael Gaines, P.E., MGA Structural Engineers, mg@mgase.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.