

**GMS, INC.**  
CONSULTING ENGINEERS  
611 NORTH WEBER, SUITE 300  
COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935  
TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E.  
ROGER J. SAMS, P.E.  
GREGORY R. WORDEN, P.E.  
THOMAS A. McCLERNAN, P.E.

KEN L. WHITE, P.L.S.  
DAVID R. FRISCH, P.L.S.  
MARK A. MORTON, P.E.  
JASON D. MEYER, P.E.

November 11, 2011

Mr. Wes Weaver, President  
Weaver Construction Management, Inc.  
3679 South Huron Street, Suite 404  
Englewood, CO 80110

***Via Email to: wes@weavergc.com***  
***No Hard Copy to Follow***

Re: Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)  
Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

|                        |  |
|------------------------|--|
| Submittal No.:         | 06602-001B   |
| Date of Submittal:     | November 10, 2011                                  |
| Title:                 | FRP Parshall Flume for Headworks Building          |
| Specification Section: | 06602 – Fiberglass Reinforced Plastic Fabrications |
| Manufacturer:          | Plasti-Fab   |

The referenced submittal has been stamped "***Make Corrections Noted***". Our comments are as follows:

1. Note No. 1 under "The nested flume" on the TYPICAL SPECIFICATIONS NESTED PARSHALL FLUMES states, "1. will be constructed such that its approach and throat floor of the smaller flume will sit flat on top of the larger flume's approach and throat sections." This is an incorrect statement. The smaller flume shall be placed inside of the larger flume at the elevations shown on Drawing HW-16 attached to this shop submittal.
2. Note No. 2 under INSTALLATION COMMENTS FOR NESTED FLUMES states, "2. Place the flume to be nested so that flat approach and throat sections rest directly on approach and throat of larger unit." This again is an incorrect statement. We request this be revised to indicate the smaller flume shall be placed at the elevations shown on Drawing HW-16 attached to this shop submittal.
3. All other items noted in prior GMS, Inc. correspondence appear to have been satisfactorily addressed.

Mr. Wes Weaver  
November 11, 2011  
Page 2

Please call if you should have any questions.

Sincerely,

A handwritten signature in blue ink that reads "David R. Frisch". The signature is written in a cursive style.

David R. Frisch, P.L.S.

DRF/kmw

ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, [lfmanager@lfmsdd.org](mailto:lfmanager@lfmsdd.org)  
Ms. Cindy Murray, Office Manager, Fountain Sanitation District, [fsdistrict@fsd901.org](mailto:fsdistrict@fsd901.org)  
Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., [jeff@weavergc.com](mailto:jeff@weavergc.com)  
Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., [john@weavergc.com](mailto:john@weavergc.com)  
Mr. Tyler Ammerman, Weaver Construction Management, Inc., [tammerman@weavergc.com](mailto:tammerman@weavergc.com)  
Ms. Leslie Brown, Weaver Construction Management, Inc., [leslie@weavergc.com](mailto:leslie@weavergc.com)  
cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.