GMS, INC.

CONSULTING ENGINEERS 611 NORTH WEBER, SUITE 300 COLORADO SPRINGS, COLORADO 80903-1074

TELEPHONE (719) 475-2935 TELEFAX (719) 475-2938

EDWARD D. MEYER, P.E. ROGER J. SAMS, P.E. GREGORY R. WORDEN, P.E. THOMAS A. McCLERNAN, P.E. KEN L. WHITE, P.L.S. DAVID R. FRISCH, P.L.S. MARK A. MORTON, P.E. JASON D. MEYER, P.E.

November 3, 2011

Mr. Wes Weaver, President Weaver Construction Management, Inc. 3679 South Huron Street, Suite 404 Englewood, CO 80110 Via Email to: wes@weavergc.com No Hard Copy to Follow

Re:

Harold D. Thompson Regional Water Reclamation Facility (HDTRWRF)

Lower Fountain Metropolitan Sewage Disposal District (LFMSDD)

Dear Wes:

Reference is made to your shop submittal identified as follows:

Submittal No.:

08710-001A

Date of Submittal:

October 25, 2011

Title:

Door Hardware - Frame, Door and Hardware

Specification Section:

08710

Supplier:

Southwestern Hollow Metal. Division of Cook Street Ltd.

Manufacturers:

Southwestern Hollow Metal; Colorado Doorways, Inc.; Ives;

Pemko; Von Duprin; Corrim Company

The referenced submittal has been stamped "No Exception Taken" and "Submit Specified Item". Our comments are as follows. The following numbering system references the response letter to Shop Submittal No. 08710 dated September 30, 2011 as prepared by GMS, Inc. Responses by the product supplier and manufacturers reference the number system in this letter as well.

1. No Exception Taken

- 2. We acknowledge the supplier/manufacturer is not providing the low E glass. We request the General Contractor coordinate with the glass supplier and provide a shop submittal with the necessary information.
- 3. The glass supplier's shop submittal should identify the appropriate labeling to be placed on each individual piece of glass for inspection on site. *Submit Specified Item*

4. No Exception Taken

5.a. No Exception Taken

- Please reference Addendum No. Six (6) for the mechanical pushbutton assembly that will be required.
- 5.b. No Exception Taken to the kick plate proposed for use and the door silencer.
- 5.c. No Exception Taken to the stainless steel hinge and manufacturer proposed for use.

5.d. Submit Specified Item

 The cut sheets provided in the resubmittal are for manual flush bolts, not for a hinge pin doorstop. Please submit a cut sheet for a hinge pin door stop that will be utilized for this project. Mr. Wes Weaver November 3, 2011 Page 2

- 5.e. No Exception Taken
- 5.f. No Exception Taken
- 5.g. No Exception Taken
- 5.h. No Exception Taken
- 5.i. No Exception Taken
- 5.j. No Exception Taken
- 5.k. No Exception Taken
- 5.l. No Exception Taken
- 5.m. Please reference Addendum No. Six (6) which provides the specification for the mechanical pushbutton security system.
- 5.n. No Exception Taken
- 5.o. No Exception Taken
- 6.a. No Exception Taken
- 7.a. No Exception Taken
- 8.a. No Exception Taken
- 8.b. No Exception Taken

David R. Frisch

Please call if you should have any questions.

Sincerely,

David R. Frisch, P.L.S.

DRF/kmw ec (letter only):

Mr. Jim Heckman, Manager, LFMSDD, Ifmanager@lfmsdd.org

Ms. Cindy Murray, Office Manager, Fountain Sanitation District, fsdistrict@fsd901.org

Mr. Jeff Burst, Project Supt., Weaver Construction Management, Inc., jeff@weavergc.com

Mr. John Jacob, Project Mgr., Weaver Construction Management, Inc., john@weavergc.com

Ms. Leslie Brown, Weaver Construction Management, Inc., leslie@weavergc.com

cc: Mr. Jerry Miller, Resident Project Representative, GMS, Inc.